

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L2	7760	delay near stage\$1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 10:49			0
2	BRS	L3	3	switch\$1controlled adj2 load	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 10:49			0
3	BRS	L4	0	2 and 3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 10:50			0
4	BRS	L5	7499	switch near load	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 10:50			0
5	BRS	L7	1735	noise near power near supply	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 10:51			0
6	BRS	L8	0	6 and 7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 10:51			0
7	BRS	L6	22	2 and 5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 11:08			0
8	BRS	L9	3	"6373342"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/13 11:08			0